



Photo No: 1 **Clyde Dump**
Date: October 11, 1995
Orientation: South
Description: Facing south from south Central Clyde Dump.



Photo No: 2 **Clyde Dump**
Date: October 11, 1995
Orientation: North
Description: Facing North from south central Clyde Dump.

EPA Region 5 Records Ctr.



355605



Photo No: 3 **Clyde Dump**
Date: October 11, 1995
Orientation: South
Description: Excavation pit on east side of Clyde dump near drainage ditch.



Photo No: 4 **Clyde Dump**
Date: October 11, 1995
Orientation: West
Description: Buried drum containing waste



Photo No: 5 **Clyde Dump**
Date: October 11, 1995
Orientation: South
Description: Raccoon Creek near the PPE.



Photo No: 6 **Clyde Dump**
Date: October 11, 1995
Orientation: West
Description: Solidified drum contents downstream of Clyde dump in Raccoon Creek.



Photo No: 7
Sample No. EZN/MEYX 44 & duplicate 45.
Date: October 11, 1995
Orientation: South
Description: Soil sample collected excavation.

Photo No: 8
Sample No: EZN/MEYX 43 & CD-TCLP-1.
Date: October 11, 1995
Orientation: South
Description: Soil sample collected from soil around drums. (Below)





Photo No: 9 **Surface Water Sample No. EZN/MEYX54.**
Date: October 11, 1995
Orientation: East
Description: Surface water sample collected from east drainage ditch.




Photo No: 10 **Sediment Sample No. EZN/MEYX94**
Date: October 11, 1995
Orientation: East
Description: Sediment sample collected from east drainage ditch.



Photo No: 11
Sample No. EZN96
Date: October 11, 1995
Orientation: West
Description: Leachate sample collected at outbreak coming from landfill in the east central drainage ditch.

Photo No: 12
Sample No: EZN/MEYX 90.
Date: October 11, 1995
Orientation: North
Description: Sediment sample collected from pond. (Below)





Photo No: 13 Sediment Sample No. EZN/MEYZ 88 and duplicate 92

* note sample number in photo is incorrect.

Date: October 11, 1995

Orientation: North

Description: Sediment sample collected from north drainage ditch.



Photo No: 14 Surface Water Sample No. EZN/MEYX 51 and duplicate 53

Date: October 11, 1995

Orientation: North

Description: Surface water sample collected from north drainage ditch.




Photo No: 15
Sample No. EZN/MEYX 50
Date: October 11, 1995
Orientation: North
Description: Surface water
sample collected downstream
of the PPE in Raccoon Creek.

Photo No: 16
Sample No: EZN/MEYX 87.
Date: October 11, 1995
Orientation: North
Description: Sediment sample
collected downstream of the
PPE in Raccoon Creek.
(Below)





Photo No: 17 Sediment Sample No. EZN/MEYZ 89
Date: October 11, 1995
Orientation: East
Description: Sediment sample taken from inside pipe.



Photo No: 18 Sediment sample No. EZN/MEYZ 91
Date: October 11, 1995
Orientation: South
Description: Sediment sample taken from Raccoon Creek

**Photo No: 19****Sample No. SW:** EZN/MEYX 55; **SED:** EZN/MEYX 97**Date:** October 11, 1995**Orientation:** East**Description:** Surface water and sediment sample collected from inside pipe.**Photo No: 20****Sample No:** EZN/MEYX 48**Date:** October 11, 1995**Orientation:** North**Description:** Background soil sample collected at 3726 County Road 223, Clyde, Ohio. (Below)